

Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Level 1 Report AS3798

Client: Shadforth's Civil Pty Ltd
Project: The Landing Stages 1,2, 4 & 5
Address: 84 Samsonvale Road, Strathpine Qld

Job No: J19/69



Version	Date	Author	Initials	Reviewer	Initials
1	25/04/20	JJ	JJ	DW	DW

Form No: W169 – Version 1 (29/05/18)











Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Table of Contents

1.0	Introduction	Page 1				
2.0	Site Description	Page 1				
3.0	Foundation Preparation 3.1 Site Stripping 3.2 Proof Rolling	Page 1				
4.0	Controlled Filling	Page 2				
5.0	Compaction Control Testing	Page 2				
6.0	Field Density Results	Page 2				
7.0	Report on Filling Operations	Page 3				
8.0	Notes	Page 3				
Annondiv	1 – General Layout Plan					
Appelluix	i – General Layout Flan					
Appendix	2 – Field Density Reports					
Appendix	Appendix 3 – Typical Site Conditions					
Appendix	4 – Site Information					



Mobile: 0438 924 637 **Fax**: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

1.0 Introduction

Wagner Soil Testing has recently completed a Level One Overview of Earthworks, in accordance with the requirements of **AS3798 – "Guidelines on Earthworks for Commercial and Residential Developments"** for The Landing – Stages 1, 2 & 4.

Controlled fill (as defined in AS 2870) was placed by Shadforth's Civil Pty Ltd. Stripping instructions, proof rolling and compaction control testing was carried out by Wagner Soil Testing (on a fulltime basis) during all earthwork's operations. Our onsite supervision component excludes assessments of fill quality and engineering properties that are outside the requirements of AS3798 – 2007, including CBR values and soil reactivity.

2.0 Site Description

The site is located at 84 Samsonvale Road, Strathpine, Qld 4500. The general location of the site is shown in the attached site plans (Appendix 1). The site is bound by existing residential developments and Four Mile Creek.

3.0 Foundation Preparation

3.1 Site Stripping

Vegetation, topsoil, and organic rich materials were stripped and stockpiled onsite prior to the commencement of filling operations. As a safety factor several test pits were excavated in the proposed fill area to assess subsurface conditions & any significant issues were noted & remediated during this phase.

3.2 Proof Rolling

All stripped areas were proof rolled prior to any fill placement. Any compressible areas with apparent movement were excavated to a firm base before any fill being placed.

4.0 Controlled Filling

Fill materials (onsite) compacted using an 815 Compactor. The natural ground in the areas of filling generally comprised of silty sandy clays (CI). The fill material used was generally as above. Moisture contents of all fill placed was monitored by Wagner Soil Testing. Total volumes of fill reached 15,079m³.

5.0 Compaction Control Testing

Compaction Control Testing was carried out by Wagner Soil Testing. Testing was carried out in accordance with the requirements of **AS3798 Table 5.1 (Minimum Relative Compaction)** and **Table 8.1 (Frequency of Field Density Tests).** During the works, one hundred & twenty-four (124) Field Dry Densities were carried out on fill materials together with Dynamic Cone Penetrometers (DCP's) over the filled zones at the completion of earthworks operations to help quantify bearing capacities.



PO Box 171 Wamuran Qld 4512 **Phone:** 07 5496 6715 **Mobile:** 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

6.0 Field Density Results

All Nuclear Field Densities carried out on the fill indicated Density Ratios greater than the specified requirement of 95% (standard compaction) & **AS3798 Table 5.1**.

7.0 Report on Filling Operations

The results obtained from Compaction Control Testing, together with observations made during earthworks operations indicate that all fill materials were placed in a controlled manner in accordance with good engineering practices. The earthworks have been carried out to meet the requirements of Level 1 Certification as per AS3798 – "Guidelines on Earthworks for Commercial and Residential Developments".

8.0 Notes

Certified / Controlled (Level 1) Fill is only an assurance of its density. There are sites where long-term consolidations of fill can occur, unrelated to its actual density. Sites where fill has been placed over inferior material and sites where the depth of controlled fill varies dramatically over short distances are sites where differential consolidations must be considered. Although all Field Densities carried out reached density ratios greater than 95% as required, some material still may have bearing ratios below 100kPa as per AS2870 – Residential Slabs & Footings depending on material composition, and unfavorable site classifications and low subgrade design strengths still may be encountered.

All compacted fill is subject to secondary (creep) settlement, which is relational to the depth of the fill. Estimated secondary settlement may be of the order of 1% to 2% of the total fill height over 15 years. There is a possibility that additional fill has been placed after the date of the last field density test or at times when Wagner Soil Testing has not been notified that filling operations are in progress. The installation of services may cause disruption of the compacted fill.

Unless otherwise stated, Level 1 Certification does not address trench backfill operations, batter slope stability, retaining wall construction, global stability analysis, acid sulfate testing and or management. The "supervision" component of this Level 1 Report is not NATA endorsed. Wagner Soil Testing must be contacted if any site levels are modified whatsoever. It is the client's responsibility to maintain site drainage after the issue of this report.

A full geotechnical site investigation / classification and foundation design for the specific ground conditions should be carried out by suitably qualified or experienced personnel prior to building. This service can be provided, if required, by contacting Wagner Soil Testing.



PO Box 171 Wamuran Qld 4512 **Phone:** 07 5496 6715 **Mobile:** 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Constraints:

This report was produced for the sole use of Shadforth's Civil Pty Ltd. This report should not be used by or depended upon for other projects or purposes on the same or other projects or by a third party. In the preparation of this report Wagner Soil Testing has relied upon information provided by the client and or their agents.

The results provided in this report are indicative of the subsurface conditions on the site only at the specific sampling or testing locations, and then only to the depths investigated along with the time the work was carried out. It is known that subsurface conditions can suddenly change due to irregular geological processes and as a result of human influences. Such changes may occur after Wagner Soil Testing's field testing has been completed.

Certain ground conditions and the materials behavior observed or contained at the test locations may alter from those which may be encountered elsewhere on the site. Should variations in subsurface conditions be encountered, then additional advice should be sought from Wagner Soil Testing and if required, amendments made.

Wagner Soil Testing cannot be held responsible for interpretations or conclusions made by others unless they are supported by an expressed statement, interpretation, outcome or conclusion given in this report.

To establish a geotechnical model as per AS1726-2017-5.2 we require extra testing. No differential settlement estimates have been calculated for this site.

For further technical support regarding this Geotechnical Report please contact Mr. Dean Wagner of Wagner Soil Testing.

Dean Wagner Managing Director

Wagner Soil Testing



Phone: 07 5496 6715 Mobile: 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Appendix 1


General Layout Plan

PROPOSED EARTHWORKS STAGES 1,2,4 & 5

84 SAMSONVALE RD, STRATHPINE FOR 'PEET LIMITED'

DRAWING LIST

18-0214-200 COVER PLAN **EARTHWORKS** 18-0214-201 GENERAL NOTES 18-0214-202 BULK EARTHWORKS LAYOUT PLAN SHEET 1 OF 4 18-0214-203 BULK EARTHWORKS LAYOUT PLAN SHEET 2 OF 4 18-0214-204 BULK EARTHWORKS LAYOUT PLAN SHEET 3 OF 4 18-0214-205 BULK EARTHWORKS LAYOUT PLAN SHEET 4 OF 4 18-0214-206 BULK EARTHWORKS TYPICAL SECTIONS SHEET 1 OF 2 18-0214-207 BULK EARTHWORKS TYPICAL SECTIONS SHEET 2 OF 2 18-0214-208 CUT AND FILL DEPTH RANGE LAYOUT PLAN SHEET 1 OF 2 18-0214-209 CUT AND FILL DEPTH RANGE LAYOUT PLAN SHEET 2 OF 2





No. OF LOTS = 108

AREA OF SITE = 15.80 ha

RP DESCRIPTION

LOT 1 ON RP57746 & LOT 1 ON RP105238

DATUM LEVEL AND LOCATION

GNSS - PIN 9900 RL 27.432 AHD LOCATED AT RP105238

LOCAL AUTHORITY: MORETON BAY REGIONAL COUNCIL

COUNCIL REFERENCE NUMBER: -

THESE DRAWINGS ARE TO BE READ IN CONJUNCTION WITH

- VEGETATION MANAGEMENT PLAN
- LANDSCAPE ARCHITECT'S PLANS
- ELECTRICAL, COMMUNICATIONS AND GAS CONSULTANT'S PLANS SAFETY IN DESIGN REPORT

WARNING! - EXISTING SERVICES

EXTREME CARE SHOULD BE TAKEN WHEN EXCAVATING IN THIS AREA. THE FOLLOWING EXISTING SERVICES ARE LIKELY TO BE PRESENT IN THE VICINITY OF THE SITE:

- ELECTRICAL CABLES
- TELECOMMUNICATIONS CABLES
- GAS MAINS
- WATER MAINS
- SEWER MAINS

THE CONTRACTOR SHOULD CONTACT THE SERVICE PROVIDER FOR FURTHER INFORMATION AND SATISFY THEMSELVES OF ANY SPECIFIC TREATMENT OR REQUIREMENTS

ontrol at 8:57 am, Feb 05, 2020

REV	DATE	DESIGN	DRAWN	REVISION DETAILS	DRAWN	STATUS
Α	29.10.19	DC	DC	ISSUED FOR CONSTRUCTION	1	ISSUED FOR
					DC	CONSTRUCTION
					ソレ	CONSTRUCTION
						APPROVED
			_			RYAN ASHWORTH RPEQ 19674
					n/	l
					DC	Kyan Ashworth



1:2500	50	0	50	100 A1
1:5000				A3

PEET LIMITED	
OCIATED CONSULTANT RPS AUSTRALIA	

(07) 3539 9500

PROPOSED DEVELOPMENT

84 SAMSONVALE ROAD

COVER PLAN

18-0214 200

GENERAL NOTES:

- THE CONTRACTOR SHALL SUPPLY ALL LABOR, MATERIALS, PLANT AND EQUIPMENT TO CONSTRUCT THE WORKS
 AS DOCUMENTED AND STRICTLY IN ACCORDANCE WITH THE RELEVANT AUTHORITY STANDARDS,
 SPECIFICATIONS AND REQUIREMENTS
- 2. THE EXISTING SERVICES THAT ARE SHOWN ON THE DRAWINGS ARE PROVIDED FOR INFORMATION PURPOSES ONLY. NO RESPONSIBILITY IS TAKEN BY THE SUPERINTENDENT OR THE PRINCIPAL FOR INFORMATION THAT HAS BEEN SUPPLIED BY OTHERS, OR ANY EXISTING SERVICES THAT MAY BE PRESENT NOT SHOWN ON THE DRAWINGS. THE CONTRACTOR SHALL VERIFY THE POSITION OF ANY UNDERGROUND SERVICES WITHIN THE AREAS OF WORKS AND SHALL BE RESPONSIBLE FOR MAKING GOOD ANY DAMAGE THERETO. ANY ALTERATION WORKS TO SERVICES WILL BE CARRIED OUT ONLY BY THE SERVICE OWNER AUTHORITY UNLESS APPROVED OTHERWISE.
- 3. ALL CONSTRUCTION ACTIVITIES UNDERTAKEN SHALL COMPLY WITH CURRENT WORKPLACE HEALTH AND SAFETY REQUIREMENTS AND LEGISLATION.
- PRIOR TO COMMENCING WORK, THE CONTRACTOR IS RESPONSIBLE FOR OBTAINING ALL RELEVANT LOCAL AUTHORITY PERMITS.
- THE CONTRACTOR SHALL NOT COMMENCE THE DEMOLITION OF ANY EXISTING BUILDINGS AND/OR STRUCTURES WITHOUT APPROVAL FROM THE SUPERINTENDENT.
- 6. THE CONTRACTOR SHALL APPLY INDUSTRY BEST PRACTICE SO WORKS SHALL NOT DISTURB OR AFFECT NEARBY RESIDENTS EITHER BY DUST, NOISE, FLOODING OR DISCONNECTION OF SERVICES. CONTRACTOR TO ENSURE THAT ACCESS AND SERVICES TO EXISTING PROPERTIES ARE AVAILABLE AT ALL TIMES.
- 7. THE CONTRACTOR SHALL VERIFY LEVELS OF EXISTING SERVICE CROSSINGS AND CONNECTION POINTS PRIOR TO COMMENCEMENT OF WORKS AND NOTIFY SUPERINTENDENT OF ANY DISCREPANCIES BETWEEN ACTUAL AND PROPOSED DESIGN LEVELS.
- 8. THESE ENGINEERING DRAWINGS ARE TO BE READ IN CONJUNCTION WITH THE APPROVED VEGETATION MANAGEMENT PLAN, WHERE APPLICABLE. WHEN IN DOUBT, ALL EXISTING TREES ARE TO REMAIN UNLESS DIRECTED OTHERWISE.
- 9. HOLD POINT: ONCE THE BASE OF MANHOLES, INSPECTION PITS, GULLIES AND FIELD INLETS FOR STORMWATER DRAINAGE AND SEWER RETICULATION HAVE BEEN POURED, CONSTRUCTION SHALL ONLY RE-COMMENCE ONCE THE SUPERINTENDENT AND/OR ENGINEER HAVE INSPECTED THE WORKS.
- 10. THE CONTRACTOR SHALL NOTE DURING THE COURSE OF THE WORKS WHEN JOINT INSPECTIONS WITH THE AUTHORITY AND THE SUPERINTENDENT ARE REQUIRED. THESE INCLUDE PRE-STARTS, SUBGRADES, PRE-SEALS, CLEARING, AND OTHER SUCH INSPECTIONS AS NOMINATED IN THE APPROVAL AND THE SPECIFICATIONS. THE CONTRACTOR SHALL ENSURE NO WORKS PROCEED PAST THE INSPECTION POINT UNTIL THE JOINT INSPECTION HAS BEEN SUCCESSFULLY COMPLETED.
- 11. THE CONTRACTOR SHALL BE RESPONSIBLE FOR PROVIDING A SAFE MOVEMENT OF TRAFFIC AND THE PROTECTION OF PERSON AND PROPERTY THROUGH AND AROUND THE SITE. THE CONTRACTOR IS RESPONSIBLE FOR ALL TRAFFIC MANAGEMENT INCLUDING THE DESIGN, CONSTRUCTION, MAINTENANCE AND REMOVAL OF TEMPORARY ROADWAYS, DETOURS, SIGNS, LIGHTS AND BARRIER AS REQUIRED STRICTLY IN ACCORDANCE WITH THE RELEVANT AUTHORITY REQUIREMENTS.

BULK EARTHWORKS NOTES

- NOTWITHSTANDING THE EXTENTS OF CUTTING AND FILLING SHOWN ON DRAWINGS, THE SUPERINTENDENT RESERVES THE RIGHT TO ADJUST THE FINISHED SURFACE LEVELS AND EARTHWORKS EXTENTS THROUGH WRITTEN DIRECTION.
- THE CONTRACTOR SHALL UNDERTAKE ALL CLEARING USING INDUSTRY BEST PRACTICE INCLUDING CONSIDERATION OF FAUNA RELOCATION.
- THE CONTRACTOR SHALL UNDERTAKE ALL EARTHWORKS IN ACCORDANCE WITH AS3798-2007 AND LOCAL AUTHORITY REQUIREMENTS. LEVEL 1 SUPERVISION IS REQUIRED.
- 4. THE CONTRACTOR SHALL CONSIDER LOADS GENERATED BY THE EARTHWORKS OPERATIONS SO AS TO AVOID DAMAGE TO ALL PIPES, SERVICES AND STRUCTURES.
- THE EARTHWORKS DRAWINGS ARE TO BE READ IN CONJUNCTION WITH THE PROJECT'S SEDIMENT AND EROSION CONTROL PLAN, WHERE APPLICABLE.
- 6. THE CONTRACTOR SHALL BE RESPONSIBLE FOR THE PLANNING, DESIGN, CERTIFICATION, IMPLEMENTATION AND MAINTENANCE OF AN EROSION AND SEDIMENT CONTROL PLAN THAT IS COMPLIANT WITH THE INTERNATIONAL EROSION CONTROL ASSOCIATION (IECA) GUIDELINE 'BEST PRACTICE EROSION AND SEDIMENT CONTROL' AND RELEVANT COUNCIL POLICIES.
- 7. THE CONTRACTOR IS RESPONSIBLE FOR ENGAGING THE SERVICES OF AN RPEQ GEOTECHNICAL ENGINEER TO DESIGN / CERTIFY BULK EARTHWORKS FILLING WHERE DEPTHS OF FILL EXCEED THAT COVERED BY AS3798-2007. THE CONTRACTOR IS WHOLLY RESPONSIBLE FOR COORDINATING THEIR WORKS TO OBTAIN THIS CERTIFICATION.
- 8. THE CONTRACTOR IS RESPONSIBLE FOR DESIGNING AND CERTIFYING ALL RETAINING WALLS SHOWN ON THE PLAN AND SHALL BE IN ACCORDANCE WITH THE RELEVANT AUTHORITY STANDARDS / AUSTRALIAN STANDARDS. THE CONTRACTOR SHALL PROVIDE A FORM 15 & 16 TO COVER ALL WORKS

RECEIVED

By Document Control at 8:57 am, Feb 05, 2020


EV DATE DESIGN DRAWN


Α	29.10.19	ВС	DC	1830ED FOR CONSTRUCTION	DC	CONSTRUCTION
			 			APPROVED BREE 10074
						RYAN ASHWORTH RPEQ 19674
					n/	Ryan Ashworth
					DC	EOD AND ON BEHALE OF DEAKLIDRAN DTY LTD





ICCLIED EOD

CLIENT	PROJECT NAME	DRAWING TITLE			
PEET LIMITED	PROPOSED DEVELOPMENT	GENERAL NOTES			
ASSOCIATED CONSULTANT RPS AUSTRALIA (07) 3539 9500	84 SAMSONVALE ROAD STRATHPINE	PROJECT No. 18-0214	DRAWING No.	REVISION	











Phone: 07 5496 6715 Mobile: 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Appendix 2

Field Compaction Tests



Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au

TESTINU	Web: www.wagnersoiltesting.com.au

Location Tested	Depth Below L	Field Moisture Content	Compaction Ratio
Lot 1 – South Side	Final Level	14.0	98.0
Lot 5 – Front	Final Level	14.3	98.1
Lot 64 – Centre	Final Level	14.2	98.1
Lot 65 – Centre	Final Level	13.8	97.9
Lot 66 – Centre	Final Level	17.3	95.4
Lot 67 – Centre	Final Level	15.4	98.4
Lot 68 – Centre	Final Level	15.2	97.9
Lot 69 – Rear	Final Level	18.0	99.2
Lot 70 – Rear	Final Level	13.9	96.4
Lot 71 – Centre	Final Level	15.4	98.2
Lot 72 – Centre	Final Level	16.4	98.6
Lot 73 – Rear	Final Level	14.3	99.0
Lot 74 – Rear	Final Level	17.1	96.4
Lot 47 – Centre	Final Level	16.2	98.4
Lot 48 – Centre	Final Level	17.4	99.1
Lot 49 – Centre	Final Level	15.6	97.4
Lot 50 – Rear	Final Level	17.6	96.1
Lot 51 – Rear	Final Level	13.8	96.2
Lot 52 – Rear	Final Level	14.3	98.4
Lot 53 – Rear	Final Level	16.2	95.6
Lot 46 – Centre	Final Level	13.9	98.1
Lot 45 – Centre	Final Level	13.6	96.6
Lot 44 – Centre	Final Level	15.4	97.4
Lot 43 – Centre	Final Level	13.1	99.0
Lot 15 / 16 – Centre	Final Level	14.6	96.7
Lot 7 – Centre	Final Level	16.2	98.1
Lot 8 – Centre	Final Level	19.0	96.9
Lot 9 – Centre	Final Level	14.6	97.8
Lot 10 – Centre	Final Level	16.3	95.9
Lot 11 – Centre	Final Level	18.2	98.2
Lot 12 – Centre	Final Level	15.4	99.1
Lot 13 – Centre	Final Level	15.3	98.4
Lot 14 – Centre	Final Level	14.2	96.6
Lot 31 – Centre	Final Level	12.9	98.4
Lot 32 – Centre	Final Level	14.7	99.1
Lot 33 – Centre	1 st Lift	13.8	96.6
Lot 34 – Centre	1 st Lift	15.4	97.1
Lot 33 – Centre	2 nd Lift	16.4	98.6
Lot 34 – Centre	2 nd Lift	18.1	99.1
Lot 35 – Centre	2 nd Lift	14.3	96.6
Lot 33 – Centre (1000 Series)	Final Level	12.9	98.1
Lot 34 – Centre (1000 Series)	Final Level	14.6	96.6
Existing Dam Backfill – Centre	1 st Lift	16.7	96.7
Lot 59	2 nd Lift	16.1	95.1
Lot 60	Final Level	17.4	96.2
Lot 61	Final Level	15.4	96.1
Lot 83	1.5m Below FL	14.6	97.9



Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Lot 83	1.0m Below FL	14.3	98.8
Lot 82 / 83 – Boundary	0.5m Below FL	13.7	98.0
Lot 62 / 63 – Boundary Lot 62	Final Level	15.4	98.1
		17.6	
Lot 89	Final Level		99.0
Lot 87 / 86 – Boundary	Final Level	16.4	96.9
Lot 86 / 85 – Boundary	Final Level	18.3	98.1
Old Dam – South West Corner	11 th Lift	16.3	98.5
Old Dam – South East Corner	11 th Lift	18.4	98.3
Old Dam – South West Side	0.4m Below FL	12.9	98.1
Old Dam – South East Side	0.4m Below FL	15.1	97.4
Old Dam – North West Corner	Final Level	15.1	97.1
Old Dam – North East Corner	Final Level	14.8	96.9
Lot 31 – Centre (1000 Series)	Final Level	14.6	98.1
Lot 32 – Centre (1000 Series)	Final Level	11.9	98.0
Lot 30 – Centre (1000 Series)	Final Level	12.3	96.2
Lot 29 – Centre (1000 Series)	Final Level	16.1	98.0
Lot 35 – Centre (1000 Series)	Final Level	18.6	97.4
Lot 36 – Centre (1000 Series)	Final Level	15.4	96.1
Lot 1 – Centre (1000 Series)	Final Level	18.3	96.4
Lot 2 – Centre (1000 Series)	Final Level	20.4	98.1
Lot 3 – Centre (1000 Series)	Final Level	16.2	98.0
Lot 4 – Centre (1000 Series)	Final Level	14.9	97.4
Lot 5 – Centre (1000 Series)	Final Level	17.2	98.2
Lot 6 – Centre (1000 Series)	Final Level	16.4	99.0
Lot 19 – Centre (1000 Series)	2 nd Lift	17.4	96.4
Lot 20 – Centre (1000 Series)	2 nd Lift	19.1	98.1
Lot 21 – Centre (1000 Series)	2 nd Lift	14.7	97.4
Lot 22 – Centre (1000 Series)	2 nd Lift	15.4	96.7
Lot 23 – Centre (1000 Series)	2 nd Lift	16.7	98.4
Lot 24 – Centre (1000 Series)	2 nd Lift	15.4	97.4
Lot 16 – Centre (1000 Series)	Final Level	17.4	96.6
Lot 26 – Centre (1000 Series)	Final Level	20.0	98.1
Lot 27 – Centre (1000 Series)	Final Level	16.6	98.0
Lot 201 / 202 – Centre	Final Level	16.1	96.4
Lot 18 – Centre	Final Level	12.9	98.0
Lot 82 / 83 – Centre	Final Level	14.3	98.9
Lot 7 – Centre (1000 Series)	Final Level	17.2	99.1
Lot 8 – Centre (1000 Series)	Final Level	17.0	97.4
Lot 9 – Centre (1000 Series)	Final Level	15.6	98.2
Lot 10 – Centre (1000 Series)	Final Level	13.9	96.1
Lot 11 – Centre (1000 Series)	Final Level	15.4	98.4
Lot 12 – Centre (1000 Series)	Final Level	17.6	99.0
Lot 13 – Centre (1000 Series)	Final Level	14.8	98.0
Lot 14 – Centre (1000 Series)	Final Level	17.4	97.1
Lot 15 – Centre (1000 Series)	Final Level	16.1	97.0
Lot 35 / 36 – Centre (1000 Series)	Final Level	16.2	96.6
Lot 25 – Centre (1000 Series)	Final Level	14.2	98.5
Lot 17 / 18 – Centre (1000 Series)	Final Level	14.3	97.9



Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Lot 90 1st Lift 11.9 Lot 91 1st Lift 12.5 Lot 92 1st Lift 12.8	98.4 96.4 97.4 98.4
Lot 92 1 st Lift 12.8	97.4
	98.4
Lot 93 1 st Lift 8.4	00.1
Lot 94 1 st Lift 9.1	96.6
Lot 95 1 st Lift 8.9	96.1
Lot 96 1 st Lift 10.1	97.7
Lot 903 0.4m Below FL 11.4	98.1
Lot 903 Final Level 13.9	98.2
Lot 106 – Centre 1st Lift 11.6	97.4
Lot 103 – Centre 1st Lift 10.6	97.0
Lot 104 – Centre 1st Lift 10.1	99.1
Lot 105 – Centre 1st Lift 11.6	97.6
Lot 100 – Centre 1 st Lift 11.6	95.5
Lot 101 – Centre 1st Lift 10.8	99.0
Lot 102 – Centre 1 st Lift 11.8	97.2
Lot 97 – Centre 1 st Lift 10.6	98.1
Lot 98 – Centre 1 st Lift 10.6	95.9
Lot 99 – Centre 1 st Lift 11.2	96.2
Lot 103 – Centre 2 nd Lift 10.9	97.4
Lot 100 – Centre 2 nd Lift 11.6	97.4
Lot 101 – Centre 2 nd Lift 11.2	100.4
Lot 102 – Centre 2 nd Lift 12.4	99.6
Intersection – Road 3 / Road 1 1.0m Below FL 13.4	98.1
Intersection – Road 3 / Road 1 0.6m Below FL 14.1	97.4
Intersection – Road 3 / Road 1 0.2m Below FL 14.2	97.1
Lot 35 – North West Corner Final Level 14.2	96.4
Lot 16 0.4m Below FL 14.6	98.1
Lot 63 0.8m Below FL 15.4	97.4

CONSTRUCTION MATERIALS TESTING



Phone: 07 5496 6715 Mobile: 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Appendix 3

Typical Site Conditions



Mobile: 0438 924 637 **Fax**: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Typical Site Conditions





Shadforth's Civil Pty Ltd W182/1 CONSTRUCTION 84 Samsonvale Road, Strathpine Qld 06/06/18 MATERIALS TESTING



Mobile: 0438 924 637 **Fax**: 07 5496 6717

Email: admin@wagnersoiltesting.com.au **Web:** www.wagnersoiltesting.com.au

Typical Site Conditions





Shadforth's Civil Pty Ltd W182/1 CONSTRUCTION



Mobile: 0438 924 637 **Fax**: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Typical Site Conditions





Shadforth's Civil Pty Ltd W182/1 CONSTRUCTION

84 Samsonvale Road, Strathpine Qld 06/06/18 MATERIALS TESTING



Phone: 07 5496 6715 Mobile: 0438 924 637

Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Appendix 4

Site Information



Phone: 07 5496 6715 Mobile: 0438 924 637 Fax: 07 5496 6717

Email: admin@wagnersoiltesting.com.au Web: www.wagnersoiltesting.com.au

Information

Important Information about your Report

As a client of Wagner Soil Testing Pty Ltd you should know that site subsurface conditions cause more construction problems than any other factor. These notes have been provided to help you interpret and understand the limitations of your report.

Your report is project specific

Your report has been developed on the basis of your unique project specific requirements as understood by Wagner Soil Testing and applies only to the site investigated. Project criteria typically include the general nature of the project; its size and configuration; the location of any structure on the site; other site improvements; the presence of underground utilities; and the additional risk imposed by scope-of-surface limitations imposed by the client. Your report should not be used if there are any changes to the project without first asking Wagner Soil Testing to assess how factors that changed subsequent to the date of the report affect the report's recommendations. Wagner Soil Testing cannot accept responsibility for problems that may occur due to changed factors if they are not consulted. Our report does not take into account any existing filled ground or any other unforeseen subsurface conditions that may change anticipated site classification.

Subsurface conditions can change

A geotechnical engineering report is based on conditions that existed at the time the study was performed. Do not rely on a geotechnical engineering report whose adequacy may have been affected by: the passage of time; by man-made events, such as construction on or adjacent to the site; or by natural events, such as floods, earthquakes, or groundwater fluctuations. Always contact Wagner Soil Testing before applying the report to determine if it is still reliable. A minor amount of additional testing or analysis could prevent major problems.

Interpretation of factual data

Site assessment identifies actual subsurface conditions only at those points where samples are taken and when they are taken. Data derived from literature and external data source review, sampling and subsequent laboratory testing are interpreted by geologists, engineers or scientists to provide an opinion about overall site conditions, their likely impact on the proposed development and recommended actions. Actual conditions may differ from those inferred to exist, because no professional, no matter how qualified, can reveal what is hidden by earth, rock and time. The actual interface between materials may be far more gradual or abrupt than assumed based on the facts obtained. Nothing can be done to change the actual site conditions which exist, but steps can be taken to reduce the impact of unexpected conditions. For this reason, owners

should retain the services of Wagner Soil Testing through the development stage, to identify variances, conduct additional tests if required, and recommend solutions to problems encountered on

Your report will only give preliminary recommendations

Your report is based on the assumption that the site conditions as revealed through selective point sampling are indicative of actual conditions throughout an area. This assumption cannot be substantiated until project implementation has commenced and therefore your report recommendations can only be regarded as preliminary. Only Wagner Soil Testing, who prepared the report, is fully familiar with the background information needed to assess whether or not the report's recommendations are valid and whether or not changes should be considered as the project develops. If another party undertakes the implementation of recommendations of this report there is a risk that the report will be misinterpreted and Wagner Soil Testing cannot be held responsible for such misinterpretation.

Your report is prepared for specific purposes and persons

To avoid misuse of the information contained in your report it is recommended that you confer with Wagner Soil Testing before passing your report on to another party who may not be familiar with the background and purpose of the report. Your report should not be applied to any project other than that originally specified at the time the report was issued.

It is a requirement that the client contacts Wagner Soil Testing Pty Ltd when the exact position of the proposed building is confirmed so we can check if our Boreholes fall in the footing area four borelogs are only presumed indicative of the whole area until this is confirmed]. In the case of a cracked house investigation more testing may be required to conclude all possible causes of settlement and or movement. Initial drilling and lab testing may only identify some of the causes of the problem. Wagner Soil Testing should be contacted when additional testing is required. It is a company policy that Wagner Soil Testing are contacted if the development (including any portion and/or envelope) is sold and/or changes title as the report is only for the use of our direct client. If the development is sold and/or changes title Wagner Soil Testing must be contacted and subsequently will carry out a comprehensive site inspection - evaluation at no cost to ensure the preliminary report is relevant and no changes whatsoever have been made.

W184/1 06/06/18