

### FILL CERTIFICATE

PROJECT: Lot No 301 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_301

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 301 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 302 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_302

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 302 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 303 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_303

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 303 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 304 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_304

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 304 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 305 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_305

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 305 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 306 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_306

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 306 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 307 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_307

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 307 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 308 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_308

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 308 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 309 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_309

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 309 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 311 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_311

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 311 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 312 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_312 DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 312 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 313 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_313

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 313 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 314 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_314

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 314 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 315 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_315

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 315 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 316 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_316 DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 316 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 317 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_317

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 317 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 318 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_318

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 318 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 319 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_319

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 319 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 320 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_320

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 320 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 321 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_321

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 321 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 322 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_322

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 322 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 323 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_323

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 323 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 324 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_324

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 324 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 325 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_325

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 325 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 326 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_326

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 326 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 327 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_327

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 327 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 328 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_328

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 328 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 329 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_329

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 329 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 330 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_330

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 330 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 331 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_331

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 331 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 332 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_332

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 332 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 333 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_333

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 333 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



#### FILL CERTIFICATE

PROJECT: Lot No 334 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_334

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 334 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 335 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_335

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 335 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 336 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_336

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 336 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown



### FILL CERTIFICATE

PROJECT: Lot No 337 (as per Drawing No 12369-204-C02)

Haven Estate (Stage 3), Tarneit

CLIENT: Peets Funds Management Pty Ltd

Level 3, 492 St Kilda Road MELBOURNE VIC 3004

REPORT NO: 16087\_337

DATE: 14/06/16

# **SUMMARY**

Civil Geotechnical Services were engaged by Winslow Constructors Pty Ltd to provide inspection and testing services on the earthworks associated with Lot 337 of Haven Estate (Stage 3), Tarneit, in a manner which would satisfy the criteria for Level 1 Supervision as specified in Section 8.2 of AS 3798 - Guidelines on Earthworks for Commercial and Residential Developments - 2007. The project was classified as Type 1/2 requiring a minimum density ratio of 95.0% (standard compactive effort) within the area of fill placement.

A site inspection was conducted prior to any fill being placed on the Lot. On the completion of earthworks and after examining the test results and the materials used, we are of the opinion that the filling procedure conducted by Winslow Constructors Pty Ltd satisfied the requirements of AS 3798 in regard to the placement of fill on a Type 1/2 Project under Level 1 Supervision.

Accordingly, when classifying the site in accordance with the procedures presented in Section 2 of AS 2870 – Residential Slabs and Footings – Construction (2011), we are of the view that the bulk fill materials that were placed on this Lot by Winslow Constructors Pty Ltd can be considered as being placed in a controlled manner to a minimum density ratio of 95% (standard compactive effort).

#### LIMITATIONS

The use of this Certificate is only appropriate for the field conditions present up to 25<sup>th</sup> February 2016.

Griffin Brown